

TEXAS CEMETERY RESTORATION LLC



MONUMENT DESCRIPTION

Monument Type	tablet w/base
Monument Style	Historic
Material of Top/Color	marble/white
Material of Base	limestone/white
Footstone Quantity	1

MONUMENT SIZE (Feet)

Monument Width	1.75
Monument Depth	1
Monument Height	3
Overall Size	2.75

MONUMENT CONDITION

Levelness	unlevel
Monument Position 1	fallen
Monument Position 2	broken
Security of Top	Loose
Needs Cleaning	yes
Soil Severity (1-5) <small>5 = very soiled</small>	5
Soiling Type 1	soiling
Soiling Type 2	biological microbes



Texas Cemetery Restoration LLC
 10122 Cherry Tree Lane Dallas, Texas 75243
 James "Rusty" Brenner - Owner/Craftsman 214.686.0014
 Daniel Kieninger - Craftsman 214.476.8654

CEMETERY:		BEAR CREEK
CITY/COMMUNITY		LAVON
COUNTY	COLLIN	SECTION
STATE	TEXAS	ROW
DATE	05/2012	GRAVE
LONGITUDE		
LATTITUDE		

SURNAME	Cliff
FIRST NAME 1	Mary
FIRST NAME 2	

CONSERVATION PRIORITY

Priority (1-3)	1
1 = Immediate attention	
2 = Needs attention in 2-3 years	
3 = Should be reevaluated in 3-5 years	

REPAIR RECOMMENDATIONS

Epoxy broken pieces back together.
 Fill Cracks with Jahn color matched restorative mortar.
 Trim tablet bottom square
 Mortar tablet monument into slotted base.

LEVELING + CLEANING RECOMMENDATIONS

Safely lift monument from current position
 Remove old foundation and replace with suitable foundation for monument type and size
 Level monument base and align with neighboring monuments
 Remove all failed setting masonry and compounds and replace the setting material
 Safely clean monument with appropriate cleaning solution and technique

PRICING: Pricing is valid until 05/31/2013

Cleaning	\$40.00
Leveling w/ footstone	\$145.00
Repairs	\$315.00
Total + local tax	\$500.00

COMMENTS

Prices listed above are based on a project size totalling \$5,000 or more. All information given and and recommendations made herein are believed to be accurate, but not guaranteed.

Texas Cemetery Restoration LLC

TEXAS CEMETERY RESTORATION LLC



MONUMENT DESCRIPTION

Monument Type	tablet w/base
Monument Style	Historic
Material of Top/Color	marble/white
Material of Base	limestone/white
Footstone Quantity	1

MONUMENT SIZE (Feet)

Monument Width	1.75
Monument Depth	1
Monument Height	3
Overall Size	2.75

MONUMENT CONDITION

Levelness	unlevel
Monument Position 1	broken
Monument Position 2	fallen
Security of Top	Loose
Needs Cleaning	yes
Soil Severity (1-5) <small>5 = very soiled</small>	5
Soiling Type 1	soiling
Soiling Type 2	biological microbes



Texas Cemetery Restoration LLC
 10122 Cherry Tree Lane Dallas, Texas 75243
 James "Rusty" Brenner - Owner/Craftsman 214.686.0014
 Daniel Kieninger - Craftsman 214.476.8654

CEMETERY:		BEAR CREEK
CITY/COMMUNITY		LAVON
COUNTY	COLLIN	SECTION
STATE	TEXAS	ROW
DATE	05/2012	GRAVE
LONGITUDE		
LATTITUDE		

SURNAME	B
FIRST NAME 1	E.A.
FIRST NAME 2	

CONSERVATION PRIORITY

Priority (1-3)	1
1 = Immediate attention	
2 = Needs attention in 2-3 years	
3 = Should be reevaluated in 3-5 years	

REPAIR RECOMMENDATIONS

Remove excess concrete from monument foundation.
 Recommend replica. Pricing will vary depending on the monument.

LEVELING + CLEANING RECOMMENDATIONS

Safely lift monument from current position
 Remove old foundation and replace with suitable foundation for monument type and size
 Level monument base and align with neighboring monuments
 Remove all failed setting masonry and compounds and replace the setting material
 Safely clean monument with appropriate cleaning solution and technique

PRICING: Pricing is valid until 05/31/2013

Cleaning	\$40.00
Leveling w/ footstone	\$145.00
Repairs	\$40.00
Total + local tax	\$225.00

COMMENTS

Prices listed above are based on a project size totalling \$5,000 or more.
 All information given and recommendations made herein are believed to be accurate, but not guaranteed.

Texas Cemetery Restoration LLC

TEXAS CEMETERY RESTORATION LLC



MONUMENT DESCRIPTION

Monument Type	tablet w/base
Monument Style	Historic
Material of Top/Color	marble/white
Material of Base	limestone/white
Footstone Quantity	1

MONUMENT SIZE (Feet)

Monument Width	1.75
Monument Depth	1
Monument Height	3.25
Overall Size	3

MONUMENT CONDITION

Levelness	unlevel
Monument Position 1	fallen
Monument Position 2	broken
Security of Top	Loose
Needs Cleaning	yes
Soil Severity (1-5) <small>5 = very soiled</small>	5
Soiling Type 1	soiling
Soiling Type 2	biological microbes



Texas Cemetery Restoration LLC
 10122 Cherry Tree Lane Dallas, Texas 75243
 James "Rusty" Brenner - Owner/Craftsman 214.686.0014
 Daniel Kieninger - Craftsman 214.476.8654

CEMETERY:	BEAR CREEK	
CITY/COMMUNITY	LAVON	
COUNTY	COLLIN	SECTION
STATE	TEXAS	ROW
DATE	05/2012	GRAVE
LONGITUDE		
LATTITUDE		

SURNAME	Crenshaw
FIRST NAME 1	Nancy A. M.
FIRST NAME 2	

CONSERVATION PRIORITY

Priority (1-3)	1
1 = Immediate attention	
2 = Needs attention in 2-3 years	
3 = Should be reevaluated in 3-5 years	

REPAIR RECOMMENDATIONS

Trim tablet bottom square Mortar tablet monument into slotted base.
--

LEVELING + CLEANING RECOMMENDATIONS

Safely lift monument from current position Remove old foundation and replace with suitable foundation for monument type and size Level monument base and align with neighboring monuments Remove all failed setting masonry and compounds and replace the setting material Safely clean monument with appropriate cleaning solution and technique

PRICING: Pricing is valid until 05/31/2013

Cleaning	\$40.00
Leveling w/ footstone	\$155.00
Repairs	\$140.00
Total + local tax	\$335.00

COMMENTS

Prices listed above are based on a project size totalling \$5,000 or more. All information given and and recommendations made herein are believed to be accurate, but not guaranteed.

Texas Cemetery Restoration LLC

TEXAS CEMETERY RESTORATION LLC



MONUMENT DESCRIPTION

Monument Type	tablet w/base
Monument Style	Historic
Material of Top/Color	marble/white
Material of Base	marble/white
Footstone Quantity	0

MONUMENT SIZE (Feet)

Monument Width	1.25
Monument Depth	0.5
Monument Height	1.5
Overall Size	1.25

MONUMENT CONDITION

Levelness	unlevel
Monument Position 1	tilted
Monument Position 2	severly unlevel
Security of Top	Secure
Needs Cleaning	yes
Soil Severity (1-5) <small>5 = very soiled</small>	5
Soiling Type 1	soiling
Soiling Type 2	biological microbes



Texas Cemetery Restoration LLC
 10122 Cherry Tree Lane Dallas, Texas 75243
 James "Rusty" Brenner - Owner/Craftsman 214.686.0014
 Daniel Kieninger - Craftsman 214.476.8654

CEMETERY:		BEAR CREEK
CITY/COMMUNITY		LAVON
COUNTY	COLLIN	SECTION
STATE	TEXAS	ROW
DATE	05/2012	GRAVE
LONGITUDE		
LATTITUDE		

SURNAME	Daniel
FIRST NAME 1	Infant
FIRST NAME 2	

CONSERVATION PRIORITY

Priority (1-3)	2
1 = Immediate attention	
2 = Needs attention in 2-3 years	
3 = Should be reevaluated in 3-5 years	

REPAIR RECOMMENDATIONS

Remove excess concrete from monument foundation.
 Fill Cracks with Jahn color matched restorative mortar.

LEVELING + CLEANING RECOMMENDATIONS

Safely lift monument from current position
 Remove old foundation and replace with suitable foundation for monument type and size
 Level monument base and align with neighboring monuments
 Remove all failed setting masonry and compounds and replace the setting material
 Safely clean monument with appropriate cleaning solution and technique

PRICING: Pricing is valid until 05/31/2013

Cleaning	\$40.00
Leveling w/ footstone	\$80.00
Repairs	\$165.00
Total + local tax	\$285.00

COMMENTS

Prices listed above are based on a project size totalling \$5,000 or more.
 All information given and and recommendations made herein are believed to be accurate, but not guaranteed.

Texas Cemetery Restoration LLC